



Funder America, Inc.
PO Box 729
200 Funder Dr.
Mocksville, NC 27028
Phone Number: (336) 751-3501

SAFETY DATA SHEET

1. Product Information

Product	Sales Location(s)
Particleboard	Funder America, Inc. 200 Funder Dr. Mocksville, NC 27028 (336) 751-3501 Funder America, Inc. 3754 Hwy 32 North Hope, AR 71801 (870) 722-3500 Funder America, Inc. 12 Crosley Ln. Sebring, FL 33870 (863) 655-0208

Synonyms: Low Pressure Melamine Board

All exposure limits are 8-hour time-weighted-averages unless otherwise noted.
OSHA PEL's and ACGIH TLV's are current values.

2. Physical Properties

Boiling Point:	N/A
Vapor Pressure:	N/A
Vapor Density:	N/A
Solubility in Water:	N/A
Specific Gravity:	24-47 PCF
Percent Volatiles:	<1
Evaporation Rate:	N/A
Appearance and Odor:	Any color board - very slight Formaldehyde odor

3. Fire and Explosion Data

Flash Point (Method Used):	N/A
Flammable Limits:	LEL N/A % UEL N/A
Extinguishing Media:	CO2, Dry Chemical, Foam, Water Fog
Special Fire Fighting Procedures:	Material has combustion characteristics similar to wood
Unusual Fire and Explosion Hazards:	Products with densities less than 33 PCF may be prone to smolder longer than wood after flames have been extinguished.

4. Health Hazard Information

Primary Routes of Exposure: Inhalation if dust is created during fabrication.
Signs and Symptoms of Overexposure:
Acute: Irritation of eyes, nose, throat and lungs
Chronic: None expected
Aggravated Medical Conditions: Respiratory Illness
Emergency and First Aid Procedures:
Inhalation: Remove to fresh air
Eyes: Flush with soap and water
Skin: Wash with soap and water
Ingestion: Give water and induce vomiting
Other: Formaldehyde has been found to be carcinogenic in testing laboratory animals

5. Stability and Reactivity

Stability: Unstable Stable
Conditions to avoid: Fire and intense heat
Incompatibilities: None known
Hazardous Decomposition Products: None known

6. Spill and Leak Procedures

Steps to be Taken if Material is Released or Spilled: Normal Housekeeping

7. Disposal Considerations

Disposal Method: In accordance with Federal, State and Local Regulations

8. Exposure Control Measures, Personal Protection

Ventilation: Not necessary unless fabricating; if so, use sufficient ventilation to keep exposures below TLV.
Respiratory Protection: Dust mask device during fabricating if necessary (use only Niosh certified devices).
Protective Clothing: Not normally necessary
Eye Protection: Safety glasses with side shields as a minimum when fabricating

9. Special Precautions

None Known: The above information listed is believed to be accurate but not warranted or guaranteed.